



720 Olive Way, Suite 1900
Seattle, Washington 98101
Phone 206.287.9130
Fax 206.287.9131

June 16, 2014

Sean Sheldrake
Project Coordinator
U.S. EPA, Region 10
1200 Sixth Avenue, M/S ECL-111
Seattle, Washington 98101

Re: May 2014 Monthly Progress Report
Administrative Settlement Agreement and Order on Consent for Removal Action
U.S. EPA Region 10 Docket No. CERCLA 10-2009-0255
Gasco Sediments Site within the Portland Harbor Superfund Site

Project Number: 000029-02.32

Dear Mr. Sheldrake:

This monthly progress report provides information required by Section VIII, Paragraph 26, of the Administrative Settlement Agreement and Order on Consent for Removal Action (Order) for actions taken in May 2014 at the Gasco Sediments Site within the Portland Harbor Superfund Site.

1. ACTIONS TAKEN IN THIS MONTH AND PROBLEMS ENCOUNTERED

The following actions and correspondences occurred in this month:

- **May 13** – Anchor QEA submitted a schematic showing the proposed path forward administrative process for performance of the Gasco Sediments Site Order and a matrix to facilitate resolution of the unresolved EPA comments on the *Draft Engineering Evaluation/Cost Analysis*.
- **May 15** – Anchor QEA submitted the Gasco Sediments Site monthly progress report to EPA.

- **May 19** – Anchor QEA performed the monthly visual monitoring of the shoreline area in the direct vicinity of the pilot cap.

2. RESULTS OF SAMPLING, TESTS, AND OTHER DATA RECEIVED

The results of the monthly visual monitoring of the shoreline area in the direct vicinity of the pilot cap are provided as Attachment A.

3. SCHEDULE OF ACTIVITIES FOR THE NEXT MONTH

Anchor QEA anticipates the following activities to occur in the next month:

- Submit the June monthly progress report.
- Complete monthly visual monitoring of the shoreline area in the direct vicinity of the pilot cap area.
- Receive EPA's comments on the proposed path forward administrative process for performance of the Gasco Sediments Site Order and resolution of the unresolved EPA comments on the *Draft Engineering Evaluation/Cost Analysis*.

4. ANTICIPATED PROBLEMS AND PROPOSED RESOLUTIONS

No problems or unforeseen conditions were encountered.

Please contact the undersigned if you have any questions or require additional information.

Sincerely,



Ryan Barth, P.E.
Assistant Project Manager



Carl Stivers, Partner
Project Manager

Attachments:

Attachment A Monthly Visual Monitoring Report for Pilot Cap Vicinity

Cc:

Bob Wyatt, NW Natural

Patty Dost, Pearl Legal Group PC

Myron Burr, Siltronic Corporation

Alan Gladstone and William Earle, Davis Rothwell Earle and Xochihua

James Peale, Maul Foster Alongi, Inc.

Lance Peterson, CDM Smith

Matt McClincy, DEQ

Dana Bayuk, DEQ



Visual Observations Log Form

Date May 19, 2014 **Project Number:** 000029-02 BG-32 Task 4a

Location: NW Natural "Gasco" Site

Project Name: NW Natural – Gasco

Monitoring Period: Monthly (Year 8)—May 2014

Time Observations Started: May 19, 2014 @ 10:00 **Time Observation Concluded:** May 19, 2014 @ 11:00

Weather Conditions: Cloudy, 58° Fahrenheit, southwest wind @ 0-3 knots.

Wave Action Observations: Light wave action (0.0 – 0.2 feet in height)

Photographs Taken: ☒ Yes ☐ No

Tidal Conditions: Willamette River level on 5/19/14 ranged in elevation from 9.69 to 10.48 feet. The Willamette River level during photos was approximately 10.43 feet measured at 10:30 (River Level Elevation Datum: Morrison Gage Height).

Observations of Erosion/Deposition: No erosion/deposition is evident along the shoreline. The shoreward extent of the cap was not visible due to high river water elevation and the extents of the organoclay mat material were also submerged. (Photo 1).

Observations of Long-term Controls (i.e., oil booms, organo-clay mat, etc.) During the observation, the Fuel and Marine Marketing (FAMM) containment boom was placed around a barge moored at the FAMM ship dock. Buoys that identify the cap area to mariners are in place as installed. The position of the FAMM oil boom, warning buoys, and a general overview of the site shoreline is shown in Photo 2.

Other Comments: No sheen is evident in or around the cap area. Photo 3 shows the water surface and shoreline immediately downriver of the sediment cap.

Recorded by: **Douglas Laffoon**

Photo 1 — *River level currently above the extents of the sediment cap (5/19/14):*



Photo 2 — *FAMM oil boom shown around barge and the mariner warning buoys in place across the pilot cap area (5/19/14):*



Photo 3 — *Conditions immediately downriver of cap area (5/19/14):*

